

📅 WEDNESDAY, MAY 19, 2021

## Deck/Surface/Equipment

Description of deck and surface. Deck: Pavers Surface: Brown/Gold Pebble Tech Picture of pool equipment.



---

## Test - Pressure Test - Leak Detection

Pressure tested all lines. All lines appear to be holding solid. Unable to pressure test far left pump (cleaner). Dye tested floor returns, held solid.

---

## Pool - Return (around)

Found leak around pool return. Patched with epoxy. Recommend proper repair.



---

## Miscellaneous

Pipe labeled main drain on pool pump may actually be a waste line. Didn't purge air into pool.



---

## Leak Status - Minimal Water Loss

Minimal water loss should be expected until repairs are completed.

📅 MONDAY, JULY 12, 2021

## Miscellaneous

---

### Pool - Skimmer - Broken Line - Deck

Found broken skimmer line under the deck. Marked deck with photo. Needs to be repaired. Plugged off skimmer pipe and shut off at valve to prevent further water loss.

