


📅 WEDNESDAY, SEPTEMBER 29, 2021

Deck/Surface/Equipment

Description of deck and surface. equipment.

Deck: Travertine Pavers Surface: Bone Gem Picture of pool equipment.



Equipment - Valve - Air Leak

Found air leak at valve. When pump is running, air is entering through the skimmer Jandy valve needs to be serviced. See picture for dysfunctional valve.





Equipment - Fitting - Air Leak

Found air leak at suction side elbow. When pump is running, air is entering the system through elbow. Fittings need to be replaced. See picture for dysfunctional fitting.



Test - Pressure Test - Leak Detection

Pressure tested all lines. All lines appear to be holding solid.



Pool - Return (around)

Found leak around pool return. Patched with epoxy. Recommend proper repair.



Pool - Skimmer - Throat

Found leak in skimmer throat where the plastic skimmer butts up to the cement pool shell. Patched with epoxy. Recommend proper repair.



Leak Status - Patched to Temporarily Prevent Water Loss

Epoxy was applied as a temporary patch to the leaking skimmer throat and pool return so that it can be ensured all leaks have been identified and all appropriate repairs have been quoted.