

Quote

Repair #231640

BILL TO

Florian Bergmann
3901 Ceitus Pkwy
Cape Coral, FL 33991

JOB SITE

Florian Bergmann
3901 Ceitus Pkwy
Cape Coral, FL 33991

QUOTE AMOUNT

\$695.00

DESCRIPTION OF WORK	QUANTITY	PRICE	TAX	TOTAL
Scheduling Discount - Customer scheduled repair within one week of leak detection.	1.00	(\$100.00)	\$0.00	(\$100.00)

Rhino Seal Skimmer Throat	1.00	\$795.00	\$0.00	\$795.00
<ul style="list-style-type: none">• Drain pool below skimmer• Repair skimmer throat (tile will not be salvageable)• Install new tile in skimmer throat*• 1 year warranty included				

**Price includes basic tile provided*

by RRLD. Customer will need to provide tile with 10% extra for cuts if custom tile is desired.

Subtotal:	\$695.00
Tax:	\$0.00
Payments:	\$0.00

Warranties & Disclaimers

Payment is expected at time of service. License **#CPC1457457**

Note:

If any of our quoted repairs are completed by another company, our leak detection warranty will be voided. A separate fee will be charged if further testing is requested.

Customer is responsible for refilling water and balancing chemicals. Please monitor water levels for 48 hours. Contact RRLD with any questions or concerns.

Well Water Disclaimer:

If you plan to refill your pool with well water, please note that it can significantly affect water chemistry and require extra work to get the pool balanced properly. To avoid delays or potential unnecessary extra costs, we recommend discussing options with your pool service to refill your pool properly.

Change Order Disclaimer:

A change order will be issued if RRLD discovers any unforeseen or unexpected work not specified above. An additional quote will be issued at that time.

Deck Disclaimer:

RRLD does not offer custom staining or textures. We will make every attempt to match the deck when applying deck patches. If an exact match is desired (color and texture), customer will need to hire a professional deck company to apply the patch.

Patch Disclaimer:

Red Rhino Leak Detection (RRLD) will make every attempt to match the existing surface when applying patches. However, due to variations of the product from the manufacturer and aging of the existing surface, it is impossible to achieve an exact match when patching. Refinishing the entire surface is the only way to ensure a consistent appearance without variation. Therefore, RRLD cannot be held responsible for color and texture variations which are unavoidable when patching.