

📅 WEDNESDAY, OCTOBER 6, 2021

## Deck/Surface/Equipment

Description of deck and surface. equipment.

Deck:

Concrete Surface: Sky Blue Picture of pool



## Equipment - Heater - Inside

Found leak inside heater. Heater needs to be serviced. &nbsp;



## Test - Complete Dye Test

Performed a complete dye test in the pool. Everything appears to be solid.

---

## Leak Status - Leaking

The pool will continue to leak at the same rate until repairs are completed.

---

## Miscellaneous

Gutters are all sealed in. Grates need be removed/broken out in order to properly test.



📅 THURSDAY, NOVEMBER 4, 2021

### Test - Water Loss - Set Up

Marked water level in pool. Water loss results will be confirmed by a (phone call).



---

📅 SATURDAY, NOVEMBER 6, 2021

### Test - Water Loss - Results - Not Leaking

Confirmed water level is holding solid. The pool is not leaking. However the gutters now do need to be broken out to properly test.

---

📅 TUESDAY, NOVEMBER 9, 2021

## Miscellaneous

Gutters are not connected to the pump. When pressure testing the gutter line from the pump, the pressure quickly builds and holds before getting to the gutters. This indicates that the gutter line is capped underground. Instead of gutters working as normal, these gutters act like an overflow. When water is added to gutters, the water is sent to waste.



---

## Test - Water Loss - Set Up

Marked water level in pool. Water loss results will be confirmed by a (phone call) on (11/10).



 THURSDAY, NOVEMBER 11, 2021

### **Test - Water Loss - Results - Not Confirmed**

Attempts were made. At this time, the results have not been confirmed, and Red Rhino will wait to hear from the homeowner if needed.