

Invoice

Issued: 08/19/2022

Due: 08/19/2022

Pool Leak #275868

BILL TO

Beth Monsour
1905 S Holly Ln
Tampa, FL 33629

JOB SITE

Beth Monsour
1905 S Holly Ln
Tampa, FL 33629

BALANCE DUE

\$0.00

DESCRIPTION OF WORK	QUANTITY	PRICE	TAX	TOTAL
Residential Pool Leak Detection	1.00	\$350.00	\$0.00	\$350.00

- Includes testing of the pool shell, plumbing lines and equipment
- 60 day warranty
- If proper repairs are scheduled within 7 days of the initial leak detection, a \$100 scheduling discount will be applied to the repair invoice

Note: Bodies of water can lose up to a 1/4 inch a day from evaporation under normal operating conditions.

Disclaimer: Fees for services will apply if water loss is due to evaporation.

Subtotal:	\$350.00
Tax:	\$0.00
Payments:	\$350.00



Payment History

DATE	PAYMENT TYPE	STATUS	DESCRIPTION	NOTES	AMOUNT
Feb 15, 2024	Credit card charge	Paid	No description	No notes	\$350.00

📅 FRIDAY, AUGUST 19, 2022

Deck/Surface/Equipment

Deck:PaversSurface:Pebble tech



Test - Pressure Test - Leak Detection

Pressure tested all lines. All lines appear to be holding solid.



Test - Complete Dye Test

Performed a complete dye test in the pool. Everything appears to be solid.

Miscellaneous

I noticed filter pretty dirty with green algae built up.



Leak Status - Not Leaking

The pool should not be leaking at this time. If you notice significant water loss, please notify us immediately.

Warranties & Disclaimers

Payment is expected at time of service. License **#CPC1457457**

Note:

Customer is responsible for refilling water and balancing chemicals. Please monitor water levels for 48 hours. Contact RRLD with any questions or concerns.

Change Order Disclaimer:

A change order will be issued if RRLD discovers any unforeseen or unexpected work not specified above. An additional quote will be issued at that time.

Deck Disclaimer:

RRLD does not offer custom staining or textures. We will make every attempt to match the deck when applying deck patches. If an exact match is desired (color and texture), customer will need to hire a professional deck company to apply the patch.

Patch Disclaimer:

Red Rhino Leak Detection (RRLD) will make every attempt to match the existing surface when applying patches. However, due to variations of the product from the manufacturer and aging of the existing surface, it is impossible to achieve an exact match when patching. Refinishing the entire surface is the only way to ensure a consistent appearance without variation. Therefore, RRLD cannot be held responsible for color and texture variations which are unavoidable when patching.

Sign Invoice

Please sign and date below for approval and return via email(redrhinocsr@redrhino.com) or fax(561-692-4814). All scheduling is on a first come first serve basis. We will contact you regarding scheduling upon receipt of the signed document

X

Date

Printed Name