

Invoice

Issued: 05/14/2025

Due: 05/14/2025

Pool Leak #467741

BILL TO	JOB SITE	BALANCE DUE
Beth Monsour 1905 S Holly Ln Tampa, FL 33629	Beth Monsour 1905 S Holly Ln Tampa, FL 33629	\$0.00

DESCRIPTION OF WORK	QUANTITY	PRICE	TAX	TOTAL
Residential Pool Leak Detection <ul style="list-style-type: none">Includes testing of the pool shell, plumbing lines and equipment60 day warrantyOnce your Leak Detection is complete, you automatically earn a \$50 credit toward any repairs you choose to schedule with us	1.00	\$375.00	\$0.00	\$375.00

Note: Bodies of water can lose up to a 1/4 inch a day from evaporation under normal operating conditions.

Disclaimer: Fees for services will apply if water loss is due to evaporation.

Subtotal:	\$375.00
Tax:	\$0.00
Payments:	\$375.00



Payment History

DATE	PAYMENT TYPE	STATUS	DESCRIPTION	NOTES	AMOUNT
Jul 25, 2025	Credit card charge	Paid	No description	No notes	\$375.00



The Pool Leak
Experts



WEDNESDAY, MAY 14, 2025

Test - Complete Dye Test

Performed a complete dye test.



Test - Pressure Test - Leak Detection

All lines are holding solid
Additional Notes: Alternative testing on all returns Passed






The Pool Leak
Experts

Deck/Surface/Equipment

Deck:Pavers Surface:Pebble tec



Leak Status - Equipment Leak

The equipment will leak, as identified in the findings, until it is fixed by a pool service professional.



Epoxy - Item Previously Epoxyed

Found existing epoxy patch: In and around the light Around the return In the tile In and around the vac line Epoxy patches can be an indication of previous leaks that could open up in the future, initiating further water loss. Epoxy patches are an indication of previous leaks that could open up in the future as the patch wears away, initiating further water loss. Recommend proper repair. Additional Notes: Wall port closed with Epoxy





The Pool Leak
Experts

Miscellaneous







The Pool Leak
Experts

Test - Water Loss - Set Up

Water level marked in: Zero Results will be confirmed by: Phone call Date of confirmation: 2025-05-15 Additional Notes: Pump off



Pool Water Level



Bucket Water Level





The Pool Leak
Experts

THURSDAY, MAY 15, 2025

Test - Water Loss - Results - Not Leaking

Confirmed water level is holding solid. The pool is not leaking. Evaporation and equipment leak.



Warranties & Disclaimers

Payment is expected at time of service. License **#CPC1457457**

Note:

Customer is responsible for refilling water and balancing chemicals. Please monitor water levels for 48 hours. Contact RRLD with any questions or concerns.

Change Order Disclaimer:

A change order will be issued if RRLD discovers any unforeseen or unexpected work not specified above. An additional quote will be issued at that time.

Deck Disclaimer:

RRLD does not offer custom staining or textures. We will make every attempt to match the deck when applying deck patches. If an exact match is desired (color and texture), customer will need to hire a professional deck company to apply the patch.

Patch Disclaimer:

Red Rhino Leak Detection (RRLD) will make every attempt to match the existing surface when applying patches. However, due to variations of the product from the manufacturer and aging of the existing surface, it is impossible to achieve an exact match when patching. Refinishing the entire surface is the only way to ensure a consistent appearance without variation. Therefore, RRLD cannot be held responsible for color and texture variations which are unavoidable when patching.