

📅 FRIDAY, JUNE 18, 2021

Miscellaneous

Vacuum demo/ vacuum new faceplate/ complete



Repair - Completed

Repair completed. Water level is 6 inches below repair Pool can be filled at your convenience Pump is off at breakers Valves were left as found/ pool mode

